

# General Environmental Incident Summary

**Incident:** 3927      **Date/Time Notice:** 10/6/2015      1306      **DEM Incident No:**

**Responsible Party:** Gibsons Energy, LLC

**Date Incident:** 10/5/2015      **Time Incident:** 0800      **Duration:**

**County:** McKenzie      **Twp:** 152      **Rng:** 101      **Sec:** 18      **Qtr:**

**Lat:** 47.97929      **Long:** -103.66120      **Method:** Interpolation from map

**Location Description:** Alexander Station 4156, McKenzie County, ND.  
North 9.25 miles on Highway 200 from Alexander, ND. Station on left side of road at Highway 200 and 39th St NW.

**Submitted By:** Bridget Sedlack      **Affiliation:**

**Address:** 3819 Towne Crossing Blvd

**City:** Mesquite      **State:** TX      **Zip:** 75150

## Received By:

**Contact Person:** Bridget Sedlack  
3819 Towne Crossing, Ste 100  
Mesquite, TX 75150

**Distance Nearest Occupied Building:**

**Release Contained:** Yes

**Type of Incident:** Getty box overflow

**Description of Released Contaminant:** Crude oil

**Volume Spilled:** 2.50 barrels

**Ag Related:** No

**EPA Extremely Hazardous Substance:** Unknown

**Reported to NRC:** Unknown

## Cause of Incident:

Driver arrived at station and noted crude oil overflowing from Getty box of Lane 4 offload. Driver stated that header valve was open and that the dust cap was not completely closed (one dog ear down).

## Risk Evaluation:

None

**# of Fatalities:** 0      **# of Injuries:** 0      **Affected Medium:** 03 - soil

## Potential Environmental Impacts:

Soils

## Action Taken or Planned:

Absorbant & Safety Solutions hired to clean up. Hydrovac'd 1/3 of soil and all of surface fluid. Skid steer skimmed 3 to 4 inches of soil from remaining contaminated area. New material brought in and leveled. 3 samples taken from 3 major pooling areas.

**Wastes Disposal Location:** Gibson Process Recovery Disposal (PRD) Facility, Williston, ND

## Agencies Involved:

## **Updates**

---

**Date:** 10/6/2015    **Status:** Reviewed - Follow-up Required

**Author:** Tintes Schiwal, Emily

**Updated Volume:**

**Notes:**

This is a spill at a transportation off-loading facility. Followup should occur to ensure proper cleanup.

---

**Date:** 10/28/2015    **Status:** Inspection

**Author:** Washek, Sandi

**Updated Volume:**

**Notes:**

Arrived on site at 8:55 a.m. Weather was overcast with wind out of the NW at 30 mph. Temperature was 31 degrees F.

The spill is located on the Enbridge site. GPS: N47.98027, W103.66354. An Enbridge rep showed NDDoH inspector the site of the spill. The area has been cleaned up by absorbent solutions. They used trucks to vacuum all the free oil solution and removed the contaminated soil. New soil has been placed on the site. No water was impacted by the spill due to the area being within a containment dike. No additional followup needed.